

494-14

**STORMWATER MANAGEMENT REPORT  
FOR  
11 Main St,  
Framingham, MA**

**INTRODUCTION:**

The proposed project is located on the 5,991 s.f vacant property, which is bounded by Main Street, Framingham, a residential property and a real estate office. The project involves the construction of a 3 story commercial building with accompanying/adequate parking per city of Framingham requirements.

The existing hard compacted gravel finish at 11 Main St, Framingham is in an impervious condition and the site right now is serviced with two existing catch basins for rain water run off.

The construction of the proposed development will not cause an increase in impervious area and therefore does not require a recharge system per D.E.P. requirements. All roof runoff will be directed to downspouts with splash blocks and directed to the existing catch basins. The compacted crushed stone pavement is to be returned to its existing condition which is also directed to the existing catch basins.

During construction the existing catch basins shall be wrapped in filter fabric to ensure no debris can enter. This filter fabric must then be cleaned and or replaced biweekly. At the end of the construction process the catch basins must be cleaned thoroughly to ensure they are back working to their maximum potential.

If you have any questions or desire additional information please feel free to call.

Sincerely,

---

Peter Nolan